

Pola spasial kualitas air tanah dangkal di DAS Cijurey Kabupaten Majalengka Jawa Barat = Spatial pattern Of shallow groundwater quality in DAS Cijurey Regency Of Majalengka West Java

Tika Mutiara, author

Deskripsi Lengkap: <http://lib.ui.ac.id/detail?id=20509685&lokasi=lokal>

Abstrak

ABSTRAK

Mengingat disaat kebutuhan air melonjak, diperlukan alternatif untuk memperoleh air bersih. Salah satunya dengan cara memanfaatkan keberadaan airtanah dangkal. Akan tetapi tidak semua airtanah dangkal memiliki kualitas yang baik untuk dikonsumsi. Dengan itu, penelitian ini bertujuan mendeskripsikan pola spasial kualitas air tanah dangkal serta mendeskripsikan kaitan antara pola spasial kualitas air tanah dengan litologi, penggunaan lahan dan kedalaman muka air tanah di DAS Cijurey, Kabupaten Majalengka. Terdapat dua jenis parameter yang digunakan, yaitu fisik dan kimia. Pengukuran kualitas air tanah dangkal dilakukan pada bulan November tahun 2019. Hasil penelitian menunjukkan persebaran wilayah kualitas air tanah dan hubungan antara air tanah dengan ketiga faktor pengaruh di DAS Cijurey. Dengan jumlah sampel yang digunakan adalah 41 titik, pengambilan sampel kualitas air tanah dengan metode purposive random sampling. Sebagaimana, parameter yang diukur akan dibandingkan dengan 3 baku mutu yaitu, Peraturan Menteri No.492/MENKES/PER/IV/2010, Peraturan Pemerintah Republik Indonesia No.82 th.2001, dan Peraturan Menteri kesehatan RI No.01/Birhukmas/1975. Setelah itu didapatkan hasil kualitas air yang layak (6 sampel) dan tidak layak (35 sampel) untuk dikonsumsi. Serta, faktor yang mendominasi dari penggunaan lahan yaitu permukiman, untuk litologi yang mendominasi ialah batuan vulkanik tak terurai, dan kedalaman muka air tanahnya yang kedalamannya 0-5 m.

ABSTRACT

Considering when the water needs to surge, an alternative is needed to obtain clean water. One of them by utilizing the presence of shallow groundwater. However, not all shallow groundwater has good quality to consume. Thus, the study aims to describe the shallow quality spatial pattern of the groundwater and describe the link between the spatial pattern of groundwater quality with litology, land use and groundwater IN DAS Cijurey, Majalengka regency. There are two types of parameters used, namely physical and chemical. The shallow groundwater Quality measurement was carried out in November 2019. The results showed the territorial distribution of groundwater quality and the connection between groundwater and the three influence factors at DAS Cijurey. With the number of samples used is 41 point, groundwater quality sampling with purposive random sampling method. As, the parameters measured will be compared to 3 quality standards namely, Ministerial Regulation No. 492/Menkes/PER/IV/2010, Government regulation of the Republic of Indonesia No. 82nd. 2001, and Regulation of the Minister of Health RI No. 01/birhukmas/1975. After that, a decent water quality result (6 samples) is not feasible (35 samples) for consumption. As well, the dominating factors of land use i.e. settlement, for the dominating litology is the unraveling volcanic rock, and the depth of the water in its depths of 0-5 meters.